

Work Order Bid (ID)

WORK TO BE PERFORMED IN ACCORDANCE WITH 2011 TENNESSEE WEATHERIZATION FIELD GUIDE and ANY LOCAL CODES. QUESTIONS SHOULD BE DIRECTED TO EAST TENNESSEE RESOURCE AGENCY - WEATHERIZATION DEPT.

WORK ORDER INFORMATION

Work Order Name: WO/60006EA0542/2
Work Order Type: Weatherization
Audit Name: 60006EA0542REV

CLIENT INFORMATION

Client ID: 60006EA0542

AGENCY INFORMATION

Agency:East Tennessee Human Resource AgencyAgency Phone:(865) 691-2551Address:9111 Cross Park Drive, Suite D100Fax:(865) 531-7216

Knoxville, TN 37923 *Email Address:*

Company Name & License Number:	
Contractor's Signature:	

COMMENT

SITE BUILT 1962 APPROX. 1485 SQ. FT. EXTERIOR BRICK FUEL ELECTRIC CERTIFIED FIRM RENOVATOR REQUIRED AUDIT PERFORMED 6/21/2011

Measures

Measure 1 Lig	hting Retrofits			Componen	<i>ts</i> LT1			Inspected
Comment Contra	ctor to discuss with home CFL's.	owner to d	ecide t	he most effic	cient area	as to		
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Lighting	Compact Fl 18 Watt	Each Lamp	6					
2 Labor	Compact Fl 18 Watt	Each Lamp	6					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
	/H Pipe Insulation	Vater Line		Componen	ts			Inspected
	/H Pipe Insulation	Vater Line		Componen Estimated			Actual	Inspected
	•	Vater Line <i>Units</i>	Qty	•		- Oty		Inspected Total
Comment 6 Ln. F	Ft. @ Each Hot and Cold V		-	Estimated		Qty	Actual	
Comment 6 Ln. F # Material / Labor	Tt. @ Each Hot and Cold V	Units	Qty	Estimated		Qty	Actual	
Comment 6 Ln. F # Material / Labor 1 Insulation	Ft. @ Each Hot and Cold V Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
Comment 6 Ln. F# Material / Labor1 Insulation2 Labor	Ft. @ Each Hot and Cold V Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
Comment 6 Ln. F# Material / Labor1 Insulation2 Labor	Ft. @ Each Hot and Cold V Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
Comment 6 Ln. F# Material / Labor1 Insulation2 Labor	Ft. @ Each Hot and Cold V Description / Comment DHW Pipe Insulation	Units Each Each	Qty 1 1	Estimated			Actual	
Comment 6 Ln. F# Material / Labor1 Insulation2 Labor	Ft. @ Each Hot and Cold V Description / Comment DHW Pipe Insulation	Units Each Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
# Material / Labor 1 Insulation 2 Labor Other Detail	Ft. @ Each Hot and Cold V Description / Comment DHW Pipe Insulation	Units Each Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
# Material / Labor 1 Insulation 2 Labor Other Detail	Ft. @ Each Hot and Cold V Description / Comment DHW Pipe Insulation	Units Each Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

Measure 3 DW	/H Tank Insulation			Componen	ts			Inspected
Comment			Estimated				Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Hot Water Equip	m DHW Tank Insulation	Each	1					
2 Labor	DHW Tank Insulation	Each	1					
Other Detail						1		
] []		
			Measur	e Sub Total:] []	Sub Total:	
Field Notes:			mouour	o oub rotuii				
Comment Replace	oor Ins. R-19 be 100 Sq. Ft. of Missing F and Repair 500 Sq. Ft. of ex		nsulati	Floor Insula	ation.			Inspected
# Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	100		Total			Total
2 Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	100					
Other Detail	7							
			Measur	e Sub Total:]]	Sub Total:	
			Measur	e oub rotal.				
Field Notes:								

Measure 5 Re Comment 18 Cu.	frigerator Rplcmnt Ft. Energy Star			Componen	ts		1	Inspected
	3, - 11		Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Refrigerators	Energy Star - Any	Each	1					
Other Detail								
]	Out Tatal	
			Measur	e Sub Total:			Sub Total:	
	ic Ins. R-11 ACCESS IS ON THE CAR	RPORT.		Componen	ts A1		,	Inspected
		RPORT.		Componen Estimated			Actual	Inspected
		RPORT. <i>Units</i>	Qty	•		Qty		Inspected Total
Comment ATTIC	ACCESS IS ON THE CAR		Qty 1485	Estimated	1	Qty	Actual	
Comment ATTIC # Material / Labor	ACCESS IS ON THE CAR Description / Comment Attic Insulation - Blown	Units	_	Estimated	1	Qty	Actual	
Comment ATTIC # Material / Labor 1 Insulation	ACCESS IS ON THE CAR Description / Comment Attic Insulation - Blown Cellulose - R-11 Attic Insulation - Blown	<i>Units</i> SqFt	1485	Estimated	1	Qty	Actual	
Comment ATTIC # Material / Labor 1 Insulation 2 Labor	ACCESS IS ON THE CAR Description / Comment Attic Insulation - Blown Cellulose - R-11 Attic Insulation - Blown	<i>Units</i> SqFt	1485	Estimated	1	Qty	Actual	
Comment ATTIC # Material / Labor 1 Insulation 2 Labor	ACCESS IS ON THE CAR Description / Comment Attic Insulation - Blown Cellulose - R-11 Attic Insulation - Blown	<i>Units</i> SqFt	1485	Estimated	1	Qty	Actual	
Comment ATTIC # Material / Labor 1 Insulation 2 Labor	ACCESS IS ON THE CAR Description / Comment Attic Insulation - Blown Cellulose - R-11 Attic Insulation - Blown	<i>Units</i> SqFt	1485	Estimated	1		Actual	
Comment ATTIC # Material / Labor 1 Insulation 2 Labor	ACCESS IS ON THE CAR Description / Comment Attic Insulation - Blown Cellulose - R-11 Attic Insulation - Blown	<i>Units</i> SqFt	1485	Estimated Unit Cost	1		Actual Unit Cost	
# Material / Labor 1 Insulation 2 Labor Other Detail	ACCESS IS ON THE CAR Description / Comment Attic Insulation - Blown Cellulose - R-11 Attic Insulation - Blown	<i>Units</i> SqFt	1485	Estimated Unit Cost	1		Actual Unit Cost	

<i>Measure</i> 7 Fix Fai	Improper Venting Kitch	en Exhaus	st	Componen	ts		I	nspected
Comment Vent e	xisting exhaust pipe prope	rly through	n attic	to exterior.				
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecified	See the User Defined Measure for a list of materials.	Each	1					
Other Detail						_		
			Measu	re Sub Total:] ,	Sub Total:	
Field Notes:								
		Work Or	der Gra	and Total:		Gran	d Total:	